

Leica Geosystems Hotfix

Product **Leica Cyclone 9.1.4 Hotfix**
Date May 18, 2016
From Bill Wallace, Senior TLS Software Product Manager

Contents

LEICA CYCLONE 9.1.4 HOTFIX	2
Bug fix for Import Panoramic Images.....	2
Instructions	2
Compatibility	2

Leica Cyclone 9.1.4 Hotfix

Bug fix for Import Panoramic Images

This hotfix installer repairs reported problems with Cyclone 9.1.4 running out of memory when the *Import Panoramic Images* command is importing and processing panoramic images captured by external camera devices, such as iSTAR.

This hotfix has been tested on multiple collections of data of at least 50 plus setups. For data imports in excess of several hundred setups, if the error persists, we suggest the import process be broken up into groups of 100 or less setups.

Instructions

1. Ensure the Cyclone application is closed.
2. Copy the **Cyclone914Hotfix.exe** to your desktop.
3. Run the hotfix installer.
4. The installer will guide you through the final installation.
5. If for any reason you wish to uninstall the hotfix, simply run the installer again. You will be prompted to remove the installed hotfix.

Compatibility

This hotfix is for Cyclone 9.1.4 only.